

# Worsbrough Banking Replacement Works

## Progress Update 11 August 2023



### North-West – ‘Shallows’

New ‘rock mattress’ wall installed, and topsoil laid



Accessible peg area currently enabling equipment access to Kip’s Wall



### North-East – ‘Kip’s Wall’

Intersection between plasticised platforms and wall constructed



Wall excavated ready for scaffolding to be installed to carry out repair work



### South Side

Excavation of the old boat house area completed.



Lower-level wall being demolished.

